S-180 Chamberlin House Westover Private

c. 1870-1880

The Chamberlin House is a c. 1870-1880 two-story, three-bay cross-gabled frame house which stands on the west side of MD 413 in Westover. It is one of a half-dozon cross-gabled dwellings which supply part of the modest housing stock in the village. Most of these structures have been compromised to some degree with the alteration of sash or the replacement of siding.

Maryland Historical Trust State Historic Sites Inventory Form

Magi No. 2001805504

DOE __yes __no

1. Nam	e (indicate pr	eferred name)		
L'ataile				
historic				
and/or common	Chamberlin Hous	e		
2. Loca	ation			
street & number	West Side of MD	413 (Crisfield West	over Road) _	not for publication
city, town We	estover	vicinity of	congressional district	First
state Maryla	and	county	Somerset	
3. Clas	sification			
Category district _X building(s) structure site object	Ownership public private both Public Acquisition in process being considered X not applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	ftV (give names an	d mailing addresse	es of all owners)
			-	
name Mrs.	. John Chamberlin			
street & number			telephone n	0.:
city, town Wes	stover	state a	and zip code MD 2	21871
		al Descriptio		
				7
courthouse, regi	stry of deeds, etc. Some	rset Clerk of Court		liber
street & number	Somerset County	Courthouse		folio
city, town Pr	incess Anne		state	MD 21853
6. Rep	resentation	in Existing	Historical Surv	veys
title				
date			federal sta	te county local
ροsitory for su	urvey records			
city, town			state	
ory, town			siate	

Condition		Check one	Check one	
excellent good	deteriorated	unaltered	X original site	
X good	ruins	_X_ altered	moved date of move	
fair	unexposed			

Survey No.

S-180

7. Description

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Chamberlin House is a c. 1870-1890 two-story three-bay cross-gabled frame house which stands on the west side of MD 413 in Westover, Somerset County, Maryland. The house faces east with the main gable running north/south.

The center hall house is supported by a minimal brick foundation and is sheated with narrow weatherboards. A layer of asphalt shingles covers the steeply pitched roof. One brick chimney with a corbelled cap rises from the center of the house.

The east elevation is symmetrically arranged with a center four-panel door flanked by window sash. Three-light sidelights and a four-light transom frame the door. A one-bay gabled porch with iron grill supports cevers the entrance bay. A 2/2 sash window is located to the right while paired 6/1 sash windows pierce the first floor to the left. The center second floor sash has been removed and 6/1 sash windows are located to each side. The center cross-gable is pierced by a pointed arch attic window. Each front corner has a narrow pilaster with a simple cap. The eaves to the roof are extended. The gable ends have a single window on each floor.

Extending to the rear is a T-kitchen wing which is finished in a simple manner.

0. 3	ignificance	barvey not b 10	
Period preh 1400 1500 1600 1700 1800 1900	10-1499 archeology-historic 10-1599 agriculture 10-1699 architecture 10-1799 art 10-1899 commerce		re religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	; dates	Builder/Architect	
check:	Applicable Criteria:A and/or Applicable Exception:A	A B C D A B C D E F G national state local	

Survey No. S-180

Prepare both a summary paragraph of significance and a general statement of history and support.

The Chamberlin House is one of a half-dozen cross-gabled dwellings which stand in Westover and comprise the modest housing stock. Most of these houses have been compromised to some extent with the alteration of sash or the replacement of siding. A minimum amount of significance is tied to this building since it contributes to the village character of this one-time railroad-oriented community.

9. Major Bibliographical References

Survey No. S-180

10. Geograp	hical Data		
Acreage of nominated proper Quadrangle name Kingsto UTM References do NOT of			Quadrangle scale 1:24000
Zone Easting	Northing	B Zone	Easting Northing
		D	
Verbal boundary descripti	on and justification		
List all states and countiestate	s for properties over	county	county boundaries
state	code	county	code
state 11. Form Pre		county	code
11. Form Pre			code
11. Form Pre	pared By	Historian	code date 5/31/84
name/title Paul Touart organization Somerset C	pared By - Architectural	Historian Trust c	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

5-180 CHAMBERLIN HOUSE KINGSTON, MU. QUAD 1972

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY





Chamberlin House Westover, Somerset County East Elevation 4/84 Paul Touart Neg./Md. Historical Trust

S-180